


1. Go to the right folder according the OS (the machine we have is 32bit OS);

이름	수정 날짜	유형	크기
WINDOWS	2019/4/2 16:39	폴더	
WINDOWS64	2019/4/2 16:39	폴더	
Hash_1.0.4.exe	2010/11/17 13:21	응용 프로그램	29 KB
Readme.txt	2019/4/2 16:42	문서	2 KB

2. Right click "up.bat", select "Run as Administrator". And it will upgrade the BIOS (Please do not do any work while upgrading, otherwise it may fail).



3. After the CMD window shows "FPT Operation Passed", turn off the machine and disconnect the power supply. After about 15s, turn on the machine and finish the upgrade.

```
C:\Windows\System32\cmd.exe
C:\Users\Administrator\Desktop\BT_Flash Programming Tool\WINDOWS>fptw /f S301a011-OKPOS.BIN

Intel (R) Flash Programming Tool. Version: 1.1.5.1162
Copyright (c) 2007 - 2015, Intel Corporation. All rights reserved.

Platform: Bay Trail
Reading HSFSTS register... Flash Descriptor: Valid

--- Flash Devices Found ---
W25Q64DW ID:0xEF6017 Size: 8192KB (65536Kb)

PDR Region does not exist.

- Reading Flash [0x800000] 8192KB of 8192KB - 100% complete.
- Erasing Flash Block [0x005000] - 100% complete.
- Programming Flash [0x005000] 4KB of 4KB - 100% complete.
- Erasing Flash Block [0x00C000] - 100% complete.
- Programming Flash [0x00C000] 16KB of 16KB - 100% complete.
- Erasing Flash Block [0x303000] - 100% complete.
- Programming Flash [0x303000] 12KB of 12KB - 100% complete.
- Erasing Flash Block [0x320000] - 100% complete.
- Programming Flash [0x320000] 4KB of 4KB - 100% complete.
- Verifying Flash [0x800000] 8192KB of 8192KB - 100% complete.
RESULT: The data is identical.

FPT Operation Passed

C:\Users\Administrator\Desktop\BT_Flash Programming Tool\WINDOWS>pause
계속하려면 아무 키나 누르십시오 . . .
```